Oroboros Instruments

O2k-Protocols SOP: O2k Quality Control 1

Mitochondrial Physiology Network 06.03(20):1-8 (2022) Version 20: 2022-04-14 ©2022 Oroboros Updates: http://wiki.oroboros.at/index.php/MiPNet06.03 POS-Calibration-SOP

O2k Quality Control 1: Polarographic oxygen sensors and accuracy of calibration

Erich Gnaiger

Oroboros Instruments

High-Resolution Respirometry Schoepfstrasse 18, 6020 Innsbruck, Austria Email: <u>instruments@oroboros.at</u> www.oroboros.at

Contents

1.	Calibration and quality control (O2k-SOP)	.2
1.1.	Preparation	.2
1.2.	The O ₂ sensor test	.2
2.	Zero oxygen calibration	.5
2.1.	Zero calibration with instrumental O ₂ background test: TIP2k	.5
2.2.	Zero calibration: manual titration of dithionite (02k-SOP)	.5
2.3.	Zero calibration: mitochondrial respiration	.5
3.	O ₂ -Calibration list: quality control	.6
4.	O ₂ sensor test and zero oxygen calibration: when?	.5
5.	O ₂ calibration window - details	.6
6.	References	.7
Suppl	ement: O2 calibration window – details (DatLab 7)	.8

Summary: High-resolution respirometry (HRR) critically depends on maintenance (<u>MiPNet19.18B</u>) and accurate calibration of the polarographic oxygen sensors (OroboPOS, POS). Calibration errors > 10 % as commonly encountered in the literature cannot be accepted in HRR. Standard operating procedures (**O2k-SOP**) are described: (1) Cleaning and preparation for use of O2k-chambers (<u>MiPNet19.03</u>); (2) Quality control for evaluation of proper POS function (SOP: O_2 sensor test, MiPNet06.03); and (3) Accurate POS calibration (<u>MitoPedia: O2-Calibration - DatLab</u>, MiPNet06.03). This is Part 1 of O2k Quality Control, a component of the *Oroboros Diagnostics Quality Management*.



Polarographic Oxygen Sensors



1. Calibration and quality control (O2k-SOP)

1.1. Preparation

- 1. Switch on the O2k, connect it to DatLab. Edit the O2k channel settings in DatLab. Clean the O2k-chambers using the DL-protocol "O2k-cleaning BeforeUse" (MiPNet19.03).
- 2. Increase the temperature of the stock of experimental medium to slightly above experimental temperature. Add 2.1-2.5 mL medium to each 2.0-mL O2k-chamber and 0.54 mL to each 0.5-mL O2k-chamber. This helps avoid the formation of gas bubbles and minimizes disturbance of the O2k temperature.
- 3. With the stirrer on (typically 750 rpm = 12.5 Hz), insert the stopper fully; check that no air bubbles are contained in the volume-calibrated chamber.
- 4. Siphon off excess medium from the top of the stopper.
- 5. Lift the stopper to the stopper spacer position.
- 6. Start a new file in DatLab and select the DL-protocol "O2-calibration air" or "O2-calibration air and zero".

1.2. The O₂ sensor test

1. **Stirrer test:** Even before final stabilization of O₂ slope neg., perform a stirrer test [F9], switching both stirrers automatically off and on. The default period is 30 s, for experiments at 37 °C. At lower experimental temperature, this period should be prolonged (60 s at 25 °C).

Quality control **a**: Upon automatic re-start of the stirrer (On), the increase of the oxygen signal should be rapid and monoexponential.



1. Stirrer test for quality control of the POS (standard 30 s) with 30 min time scale displayed with Graph Layout "02-Calibration - Background" (MiR05; 37 °C; data recording interval: 2 s. (A) DatLab 8 slope smoothing: 80 s. 2021-09-09 P2-01.DLD; (B) DatLab 7.4; slope smoothing: 40 data points. 2014-02-19 P9-01.DLD

Oroboros Instruments

2. About 20 min are required for approximate air equilibration after temperature equilibration of the incubation medium, visualized as stabilization of the Peltier power.

Quality control **b**: The raw signal (blue trace) should be between 1 and 3 μ A when at sea level up to 1000 m altitude (p_b 90 - 101 kPa,) and temperature is 25 - 37°C.

DatLab development – C:/DatLab/DL-Protocol Elle Navigation 02k IIP2k Protocols	Is/Instrumental/O2 calibration/O2 calibration_air.DLP Experiment Calibration Flux/Bloce Graph Layouts Marks Coenzyme O PhotoBiology Test Help	F F F F F F	– 🗂 × & Oroboros
O2 calibration_air ●			"
Stirre Ont	2 2 C		IO(i++)[1/2][1/2][m] 10 ● A 02 concentration 0 0 0 0 A 02 concentration 0
0 0.00.00 StirrerOnst	01500 03000 Time [HHJMMSS] 24: 02 calibration_air	0.45:00	5 8 9 0 × 3113.79 y: 4.65 y2: -9.63 000+-11/10[C]=K 3(4) y: 0
	2 2 2 3 3 3		0 0 0 0 c concentration 0 0 0 0 c concentration 0 0 0 0 c concentration 0 0 0 c concentration 0 0 0 c concentration 0 0 c concentration 0 0 c concentration 0 c concentration 0 c concentration
StirrerOnst	U.1500 U.1500 Time [HH3MKSS] 28: 02-calibration_air	10 #5.00	y2: -9.26
	2		So Temperature 50 20 0 30
20 0:00:00	0:15:00 0:30:00 Time (HH MM SSI	0:45:00	1:00:00 x: 2803.78 y: 20.37 y2: -96.28
A: Q ₂ calibration B: Q ₂ calibration B: Q calibration A: NADH calibration B: NADH calibration B: NADH calibration	O2 calibration: Chamber A Sensor number 2235 Medium MiRO5 O2 solubility factor of medium, Fax 0.9200 Air calibration source Calibration file Using mark R1 for calibration. ② Active file Update ③ Manual Value Ø2 calibration file Signal recorded [µA] ③ Active file Signal recorded [µA] ④ Active file 0.0411 ④ Manual O2 calibration values Ø2 concentration co2 [µM] POS signal: recorded [µA] Ø2 slope neg. [pmols ⁻¹ ·mL ⁻¹] ④ 179.32 R1 ⑨ 1.8021 d -0.5902 Ø2 0.000 R0 Ø2 0.001 Show details	Temperature [°C] Barometric press	sure _Δ [kPa] 94.40
MitoPedia: 02 calibration		Reset to defaults Cancel	Арріу ОК

POS Quality control (DatLab 8) using the DatLab protocol (DL-Protocol) O2_calibration_air.DLP: Plot of the O₂ sensor test (above; File 2017-02-06 P2-01.DLD; time scale is 1:05 h:min) and oxygen calibration window (below).



POS Quality control (DatLab 7) using the DatLab protocol (DL-Protocol) O2_calibration_air.DLP: Plot of the 1-hour POS performance test (above; File 2014-07-24_P4-01_O2-calib.DLD; time scale is 1:10 h:min) and oxygen calibration window (below).

3. Within 40 min, the oxygen signal should be stable with O₂ slope neg. (uncorrected) close to zero.

Quality control **c**: Signal noise should be low, reflected in the noise of the O_2 slope neg. (red trace) within ± 2 (± 4 is acceptable) pmol·s⁻¹·mL⁻¹ for both 2.0mL and 0.5-mL chambers at a data recording interval of 2 s and slope smoothing 80 s selected for calculation of the slope.

4. Set a mark on the oxygen signal (R1 – the mark is automatically named R1 when using the DL-protocol) and click on Calibration to open the DatLab O₂ calibration window. Three options are available for applying O₂ calibration values:

(1) clicking on "calibration file" loads the values from a calibration file; (2) clicking on 'Active file', uses the values

from mark R1 of the current file; (3) clicking on 'Manual', allows for the values to be entered manually. If "Active file" is selected, the R1 will be shown in **b'**. Add the O₂ solubility factor of the medium, $F_{\rm M}$ (O₂ solubility factor).

Quality control **d**: The slope uncorrected should be $\pm 1 \text{ pmol} \cdot \text{s}^{-1} \cdot \text{mL}^{-1}$ for 2.0-mL and 0.5-mL chambers if averaged across the section of the experiment marked as **R1** for air calibration (**d**). The recorded POS signal should be close to the previous calibration under identical experimental conditions. Click on Apply.

5. Close the chamber and if required, perform a zero oxygen calibration (section 4), or continue with a complete instrumental O₂ background test (<u>MiPNet14.06</u>).

Quality control **e**: After closing the chamber, select plot Y2 and set mark J°1. The O₂ slope (neg.) should be $3 \pm 1 \text{ pmol} \cdot \text{s}^{-1} \cdot \text{mL}^{-1}$ for the 2.0-mL chamber (<u>MiPNet14.06</u>) and 10.0 $\pm 4 \text{ pmol} \cdot \text{s}^{-1} \cdot \text{mL}^{-1}$ for the 0.5-mL chamber. Flux values higher than 4.0 or 14.0 pmol} \cdot \text{s}^{-1} \cdot \text{mL}^{-1} for the 2.0- or 0.5-mL chamber, respectively, may indicate a biological contamination.

Quality control **f**: The zero signal at mark R0 obtained at zero calibration (section 4) should be < 2 % of R1 (stable at < 5 % is acceptable).

2. Zero oxygen calibration

Zero calibration can be done by one of the following methods:

2.1. Zero calibration with instrumental O₂ background test: TIP2k

O2k-SOP: » MiPNet14.06 Instrumental O2 Background

2.2. Zero calibration: manual titration of dithionite (02k-SOP)

- 1. Prepare "zero solution": Dissolve two spatula tips or 20 mg of dithionite (sodium hydrosulfite, Na-dithionite, Na₂S₂O₄; <u>O2-Zero Powder</u> in the <u>OroboPOS-Service Kit</u>) in 0.5 mL deionized water. Mix in a small vial with minimum gas space. Use fresh dithionite. Dithionite is oxidized during prolonged storage and needs to be replaced.
- 2. Inject 20 μ L zero solution into the closed O2k-chamber using a <u>50 μ L</u> microsyringe.
- 3. Oxygen depletion is very rapid, and zero oxygen is reached within a few minutes. However, a few more minutes may be required until a stable signal is obtained, R_0 [µA].
- 4. Inject another 10 μL zero solution. Repeat as long as the signal responds by a further decline. Siphon off excess medium from the stopper.
- 5. On the final titration when no further decline is seen, the zero signal stabilizes quickly (< ± 0.2 or < ± 0.8 pmol·s⁻¹·mL⁻¹ for the 2.0-mL or 0.5-mL chamber respectively).
- 6. Set a mark over the stable "zero" signal (*R*₀), to complete the two-point oxygen calibration [F5]. Select Mark R1 and Mark R0 for *R*₁ and *R*₀ in the O₂ calibration window.

2.3. Zero calibration: mitochondrial respiration

Due to the high oxygen affinity of isolated mitochondria, intact cells and tissue homogenate, residual traces of oxygen are insignificant after respiratory oxygen depletion. Therefore, you can use your experimental sample for such zero-oxygen calibration. Alternatively, prepare a stock of baker's yeast, with 200 mg dry yeast in 2 mL physiological salt solution. Stir heavily to obtain a homogenous suspension of yeast cells and add 50 μ L yeast suspension into the 2-mL chamber through the cannula of the stopper, using a microsyringe.

More details: »Gnaiger et al (1995), »Gnaiger (2001).

3. O₂ sensor test and zero oxygen calibration: when?

The O₂ sensor test should be performed:

- Every day after switching on the O2k.
- During troubleshooting procedures, when switching components between the two chambers, a quick sensor test is performed after each step (stirrer test, raw sensor signal).



Oroboros Instruments

• After application of a new membrane and POS Service. In some cases, the signal of the OroboPOS improves (higher signal stability, less noise, shorter response time), when leaving the O2k switched on overnight (O2k-chambers filled with deionized H₂O at 25° C with stopper in closed position and the illumination switched off).

6

Zero oxygen calibration should be performed:

- Every few weeks.
- When working at low oxygen levels it is recommended to measure R0 before and after each measurement using the experimental sample for zero calibration (Section 2.3).

 O_2 sensor test and zero calibration are also performed at the beginning and end of the O2k-chamber test (instrumental O_2 background test).

4. O₂-Calibration list: quality control

Oroboros FileFinder: Click on the icon "O2k-Manual". Go to 'O2k-Qualtiy control and SOPs' and move to the right to open the Excel file "O2-calibration.xlsx". Save a copy of this Excel template

and paste the calibration parameters into new lines sequentially for chamber (A) and (B), thus generating a data base for quality control of instrumental calibration (<u>Gnaiger 2008</u>). Trends over time can thus be evaluated, and possible irregularities of sensor performance are quickly recognized for intervention by sensor service.

» MiPNet19.18B POS-service

5. O₂ calibration window - details



Figure 3. O₂ **calibration window – details (DatLab 8).** Upon clicking 'show details' in Calibration window oxygen calibration parameters are displayed as calculated by DatLab. (For DatLab 7, see Supplement).

In the calibration window click on "view details" to see the oxygen calibration parameters and equations calculated by DatLab.

Oroboros Instruments

Concentration: Parameters are displayed for conversion of the raw signal to concentration.

Calibration factor for concentration, F_c [μ M· μ A⁻¹]: This is the multiplication factor, F_c , calculated to convert the recorded current (corrected for the zero signal) into oxygen concentration (Supplement C - Eq. 2).

Calibration offset, a_c [µA]: This is the POS zero signal at zero oxygen concentration, which is subtracted from the current before multiplication with the calibration factor (Supplement C - Eq. 3).

Pressure: Parameters are displayed for conversion of the POS signal current to partial pressure of oxygen. These are the fundamental parameters for evaluation of signal stability over periods of several months since the POS responds to partial pressure of oxygen in the medium rather than concentration.

 p_1 [kPa]: p_{0_2} at air saturation, $p_{0_2}^*$, a function of temperature and barometric pressure.

 p_0 [kPa]: Usually p_{0_2} at zero oxygen concentration, or any other p_{0_2} at the second calibration point, p_0 .

 I_1 [µA]: POS signal as a current, at air saturation.

 I_0 [µA]: POS signal as a current, at zero oxygen concentration, or any other p_{0_2} at the second calibration point.

Oxygen consumption by the POS, $J^{\circ}_{0_2}$ [pmol·s⁻¹·mL⁻¹]: Theoretical oxygen consumption of the oxygen sensor at air saturation under experimental conditions (Supplement C - Eq. 9).

Calibration factor for pressure, F_p [kPa·µA⁻¹]: This is the multiplication factor, F_p , calculated to convert the current of the POS (corrected for the zero current) into partial pressure of oxygen (Supplement C - Eq. 5).

Calibration offset, a_p [µA]: This is the POS zero current, at zero partial pressure of oxygen, which is subtracted from the current before multiplication with the calibration factor (Supplement C - Eq. 4).

O₂ **solubility**, S_{O_2} [µM·kPa⁻¹]: a function of temperature and oxygen solubility factor of the medium (Supplement C - Eq. 7).

H₂**O vapor pressure**, $p_{H_2O}^*$ [kPa]: a function of temperature, is subtracted from the barometric pressure, p_b . (Supplement C – Eq. 9).

Volume fraction of O₂ **in dry air**: 0.20946, when multiplied with the pressure ($p_b - p_{H_2O}^*$), it yields the partial pressure of oxygen.

O2k chamber volume, *V* [mL]: The effective aqueous volume of the closed O2k-chamber.

Gain, G: The gain is used for current to voltage conversion. Gain is fixed to 1.

6. References

Gnaiger E (2001) Bioenergetics at low oxygen: dependence of respiration and phosphorylation on oxygen and adenosine diphosphate supply. Respir Physiol 128:277-97. »Bioblast link

Gnaiger E (2008) Polarographic oxygen sensors, the oxygraph and High-Resolution FluoRespirometry to assess mitochondrial function. In: Mitochondrial Dysfunction in Drug-Induced Toxicity (Dykens JA, Will Y, eds) John Wiley:327-52. » <u>Bioblast link</u>

Gnaiger E, Forstner H, eds (1983) Polarographic Oxygen Sensors. Aquatic and Physiological Applications. Springer, Berlin, Heidelberg, New York:370 pp. »Bioblast link

Gnaiger E, Steinlechner-Maran R, Méndez G, Eberl T, Margreiter R (1995) Control of mitochondrial and cellular respiration by oxygen. J Bioenerg Biomembr 27:583-96. <u>Bioblast link</u>

Acknowledgements

Supported by the NextGen-O2k and MitoFit project.



This project has received funding from the European Union's Horizon 2020 research and innovation program under grant agreement No 859770.

The project MitoFit is funded by the Land Tirol within the program K-Regio of Standortagentur Tirol.



Supplement: 02 calibration window - details (DatLab 7)

0.0		-	-
02	cal	ibrat	ion

Channel: 9A: 02 POS # 0521								
Channel label: 02								
Signal Details								
Concentration								
Calibration factor for c	oncentration []	ιM/V]	Fc	85.27	Fc = (c1-	c0) / (R1-R0)		
Calibration offset [V]			ac	0.0124	ac = (c1·R0-c0·R1) / (c1-c0)			
Pressure Oxygen pressure pO2 [kPa]				POS signal: Current Ι (μΑ)		Oxygen cons J*02 (pmo	sumtion by POS 2(POS) I/(s.ml)]	
Air calibration: p1	18.647		11	2.0678	11=R1/G	2.66 J*1 =	2.591·(l1-ap) / V	
Zero calibration: p0	0.0000		10	0.0124	10=R0/G			
Calibration factor for pressure [kPa/uA]			Fp	9.072	Fp = (p1-	p0) / (l1-l0)		
Calibration offset [µA]			ар	0.0124	ap = (p1·	10-p0-11) / (p1-p0)		
02 solubility, SO2 [µM/kPa]	9.40	cO2 = pO2	2·SO2		02k Cha	amber volume, V [r	nl] 2.00	
H2O vapor pressure pH2O* [kPa]	6.28	p02* = (pb	-pH20)*)·0.20946				
Volume fraction of O2 in dry air	0.20946							
MitoPedia: 02k-Calibratio	<u>n</u>					Cancel	Calibrate and copy to clipboard	

Figure S1. O₂ **calibration window – details (DatLab 7).** Upon clicking [F5] / Tab Details (<u>MiPNet26.06</u>) oxygen calibration parameters are displayed as calculated by DatLab.